



Install Firmware

With your browser go to <http://192.168.15.1> and log in using **user** as the username and password.

Next Click on **Management** then **Software**.

Under **Software Upgrade** click **Choose File**.

Navigate to **Downloads** and select the file ending in **.ipk**

Once the install package is selected click **Open**.

Click the **Upgrade** button. The CPE will upgrade the firmware then reboot.

Management
Account
Device Setting
Restore Default
Software

Software Upgrade

Install IPKG C:\fakepath\indoor_FW-GF

Browse Choose File indoor_FW-G...02.073.ipk

Upgrade

Device Software Version
3.3.2.0-20361-01.01.02.073-GP

Log back in and check that the firmware was upgraded under **About**.

About
Status

Status

Device Information

Model ID : DT-235

Hardware Version : V00

LTE Driver Version : 3.3.2.0-20361

WiMAX Driver Version : 4.7.0.4-44023

Serial ID : DBJVKT131500064

IMEI : 358910040033803

IMSI : Not Available

Firmware Version : 3.3.2.0-20361-01.01.02.073-GP

Firmware Creation Date : Jul 14 06:25:04 CST 2015